

L Number	Hits	Search Text	DB	Time stamp
1	236973	(power near2 line) or PLC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:26
2	179756	appliance	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 11:59
3	60535	communicat\$3 near2 interface	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:26
4	28	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:27
5	40142	serial near3 connect\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:28
6	121969	bidirection\$3 or bi-direction\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:29
9	4262	("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:31
10	2	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (serial near3 connect\$3) and (bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:33
11	3	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (serial near3 connect\$3) and (bidirection\$3 or bi-direction\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:33
12	1	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (serial near3 connect\$3) and (bidirection\$3 or bi-direction\$3)) not (((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (serial near3 connect\$3) and (bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:35
13	13	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (bidirection\$3 or bi-direction\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:35
14	10	((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (bidirection\$3 or bi-direction\$3)) not (((power near2 line) or PLC) same appliance same (communicat\$3 near2 interface)) and (serial near3 connect\$3) and (bidirection\$3 or bi-direction\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 10:35

15	12	("4442319"   "5051720"   "5777545"   "5805053"   "6005476"   "6084758"   "6175860"   "6218931"   "6229433"   "6246868"   "6288632"   "6404773"   "2002/0011923").PN.	USPAT	2004/10/05 10:50
16	1347	((power near2 line) or PLC) with appliance	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 12:00
17	40	(bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)) and ((power near2 line) or PLC) with appliance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 12:21
20	1317	(340/310.01,310.06,310.08).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 12:36
21	3067	(709/223).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 12:36
22	4382	((340/310.01,310.06,310.08).CCLS.) or ((709/223).CCLS.)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 12:37
23	11	((bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)) and ((power near2 line) or PLC) with appliance)) and (((340/310.01,310.06,310.08).CCLS.) or ((709/223).CCLS.))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 15:19
24	192	(power adj1 line) near6 communicati\$3 near2 (adapter or interface)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 15:22
25	25	(bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)) and ((power adj1 line) near6 communicati\$3 near2 (adapter or interface))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 16:09
26	167	((power adj1 line) near6 communicati\$3 near2 (adapter or interface)) not ((bidirection\$3 or bi-direction\$3) and (("120" or 120V or "240" or 240V) with ((power near2 line) or PLC)) and ((power adj1 line) near6 communicati\$3 near2 (adapter or interface))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/05 16:09